# Oil Field Environmental Incident Summary

Responsible Party: Iowa Tanklines (ITL)

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: GN-CAMBRIAN- 159-98-2536H-1

Field Name: BIG STONE Well File #: 27940

Date Incident:3/19/2015Time Incident:03:30Facility ID Number:County:WILLIAMSTwp:159Rng:98Sec:25Qtr:

Location Description: Access road at the Hess GN-CAMBRIAN - 159-98-2536 H-1

Submitted By: Jason Henry Received By:

Contact Person: Jarvis Jemtrud

6151 Highway 8 Stanley, ND 58784

General Land Use: Other - Described Above Affected Medium: Topsoil

Distance Nearest Occupied Building:0.5 MileDistance Nearest Water Well:0.5 Mile

Type of Incident: Truck Overflow

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 1.8 Barrels

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: Clean Up Concluded:

#### Risk Evaluation:

The release occurred above ground, and the source of the release has been secured.

## Areal Extent:

The release occurred on the access road at the Hess GN Cambrian 159-98-2536 H-1 location.

## Potential Environmental Impacts:

The release occurred on the access road at the Hess GN Cambrian 159-98-2536 H-1 location.

## Action Taken or Planned:

The impacted soil will be excavated and transported off-site for proper disposal.

Wastes Disposal Location: At a properly permitted disposal facility.

Agencies Involved:

## **Updates**

Date: 3/19/2015 Status: Reviewed - Follow-up Required Author: Martin, Russell

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release from a truck overflow impact on access road off location. Followup is necessary.

Date: 3/31/2015 Status: Inspection Author: Martin, Russell

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

## Notes:

3/31/2015 at 18:38, on location. Soil probe readings taken on either side of access road. EC readings all under 1500 micro-Siemens. No visible impact to access road ditches.